# Sight Flow Indicators (straight line) with **heating jacket**


Bauform 880-HM

## Application:

To keep cold- or heat- loss at sight flow indicators as low as possible, they are surrounded with a heating jacket. Within the resulting cavity, a corresponding medium can flow to avoid cold- or heat- loss.

## Dimension:

Body corresponds Bauform 880
Measures see at Bauform 880
With DIN- and ANSI - Flanges
All dimensions and all pressures



## Materials:




| | |
|---|---|
| Body: | WN 1.4408 |
| Heating jacket: | WN 1.4571 |

## Connections for heating jacket:

Buttweld ends
Inside or outside thread
Flange connection
Screwing

## Standard design:

Inside thread acc. to sketch

| Butt weld ends | Inside or outside thread | Flanged connections |
|---|---|---|
|  |  |  |

Modifications reserved

AVEMAR CZECH s.r.o. | speciální armatury pro měření a regulaci |
Branch office | Podvihovská 378/12C | 747 70 Opava 9 - Komárov | Česká republika |
Tel.: +420 553 764 015 | Fax: +420 553 654 820 | www.avemar.cz | avemar@avemar.cz |